



$d1_{h10}$ mm	$d2_{h6}$ mm	$l1$ mm	$l2$ mm	Z
1	1	38	5	2
1,5	1,5	38	5	2
2	2	38	8	2
2,5	2,5	38	8	2
3	3	38	12	2
4	4	40	12	2
5	5	50	14	2
6	6	50	16	2
8	8	63	20	2
10	10	72	22	2
12	12	73	22	2
14	14	75	25	2
16	16	82	28	2
18	18	84	28	2
20	20	104	35	2