



Command source	Step&Direction or CW/CCW
Phase	2 Phase
Input voltage	20-110 VDC of 18-80 VAC
Output current	0.5-8.0 A
Control signal voltage	5 / 24 V
Isolation resistance	100 MΩ
Max Pulse input frequency	500kHz (5V) or 200kHz (24V)
Cooling	Active
Over-voltage/current protection	Yes
Matching motors	Nema 34
Operating Temperature	0-40 °C

Itemref	Quantity	Title/Name, designation, material, dimension etc			Article No./Reference	
Drawn by Cas Jansen		Checked by	Approved by - date	File name	Date 13-9-2022	Scale 1:2

Units	mm
Tolerances	± 0.1mm unless otherwise specified

# 6019

[www.damencnc.com](http://www.damencnc.com)